

Cleaning Instructions

Comfort Flow[™], Comfort Scrape[™], Cushion Station[™], Comfort Flow[™] HD Linkable Mats, Comfort Flow[™] Modular Tile, Comfort Flow[™] HD Workstation Mats, Comfort Flow[™] W/Grit & Cushion Station[™] Food Grade

Commercial Washing Instructions

Process	Time	Water Level	Temperature
Flush	2-3 Min.	High	120° F (49°C)
Break	5-10 Min.	High	140° F (60°C)
Rinse	2 Min.	High	120° F (49°C)
Rinse	2 Min.	High	Cold

Comfort Flow and Comfort Scrape mats are fully launderable mats that perform great as anti-fatigue and flow-through mats in both wet and dry environments.

- These mats can be washed periodically to remove oil, grease and soil.
- The formula shown below does not require extensive mechanical action or drying.
- The main purpose of this formula is to dissolve grease residue by using hot water to emulsify oils and grease.
- Lay mats flat following removal from washer. Allow to cool before rolling.

Standard Washing Instructions

- Scrub with deck brush when needed using a detergent with a neutral PH.
- Rinse with a hose or pressure washer.
- Hang to dry
- Can be washed in commercial dishwashers.
- Can be autoclave sterilized.